

RETROFIT SPECIALISTS

www.mylpsolutions.com

THE RIGHT PART AT THE RIGHT PRICE. RIGHT NOW.

Goof Rings



Retrofitting to new can lights can cause problems when the hole for the old can is too large for the new can light. The newer LED style can lights are smaller in diameter than the traditional, older style ones. We can make them in any diameter and out of just about any material.

TAMPA BAY Corporate Office 2140 Range Road, Suite A | Clearwater, FL 33765 | 800-587-3310 | 727-441-9581 | 727-446-2451 fax CENTRAL FLORIDA 2119 Directors Row, Suite 5 | Orlando, FL 32809 | 800-682-4197 | 407-398-1001 | 407-398-1003 fax SOUTHEAST US 3367 W Hospital Avenue, Suite B | Chamblee, GA 30341 | 800-548-9101 | 770-817-7020 | 770-817-7021 fax NORTHEAST US 6965 Airport Highway Lane | Pennsauken, NJ 08109 | 877-619-9596 | 856-661-2442 | 856-661-2447 fax